These are the release notes for the version for Vengeance M60, Vengeance M65, Vengeance M90, and Vengeance M95.

Version numbers associated with this release:

	M60	M65	M90	M95
Software	1.0.0.37	1.0.0.10	1.0.0.37	1.0.0.11
Firmware	1.12	2.16	1.12	2.16

The 1.0.0.xx releases are not lower or older versions of the existing software – they are the latest versions available. These version numbers appear to be lower than the "Beta 2.12" software that has been on our website since January. "Beta 2.12" was the internal revision code (Beta 2, build 12) for version 1.0 of the software. Reinstalling "Beta 2.12" would be a downgrade.

Before installing this new software, please ensure that any previous version of the software is uninstalled. It is recommended that you export any profiles you have created before you uninstall the software in order to ensure that they are not lost in the reinstall process.

In addition to uninstalling any existing software, before installing this software please run the firmware update included in the ZIP file to ensure your device is running the latest version of firmware.

Firmware updaters require the mouse be plugged directly into the PC, rather than into an external USB hub port or a USB extension cable. For best results, please ensure your device is plugged into a USB 2.0 or USB 1.1 port before running the firmware update utility.

The firmware updater will erase all existing settings on the product and reset it to factory defaults.

	When the firmware updater is launched, it will first display a warning dialog. Make sure not to unplug the mouse or turn off or reboot the computer during the update process. Once the firmware update program launches, click "Update Firmware" to start the firmware update process. * Images to the left will reflect the devices version of firmware you are installing.
	Once the firmware update process is complete, click "Exit" to close the updater. *Images to the left will reflect the devices version of firmware you are installing.

This release fixes a few bugs, all of which are detailed in the table below.

M60	M65	M90	M95	Bugs fixed:
V	V	V	V	Automatic changing to a profile associate program keeps reassigned DPI buttons still working as DPI buttons even buttons are reassigned to do something else.
V	V	V	V	Fix “Advanced Options” “Basic Commands” missing Ctrl key from command sequence
V	V	V	V	Fix “Advanced Options” “Advanced Commands” missing Win key release from command sequence
V	V	V	V	Change software download link in (i) icon info dialog at “Software@Corsair “ to http://www.corsair.com/downloads
V	V			Button 4 with keystroke function, upon button 4 release it keeps repeating the assigned key.

Significant known issues:

- Firmware updaters may require the mouse or keyboard be plugged directly into the PC, rather than into an external USB hub port or a USB extension cable, such as the USB ports found on the back of the Vengeance K70 and Vengeance K95 keyboards.
- Software cannot detect devices plugged into some USB 3.0 ports. For best results, please ensure your device is plugged into a USB 2.0 or USB 1.1 port before running the firmware update utility.