

Before installing the 1.0 version of Vengeance Gaming Software, you must update your device's firmware to the latest version. The firmware update application for Vengeance Gaming peripherals can experience errors related to timing on some USB chipsets or hubs, or on USB extension cables.

Timing errors during firmware update can cause the firmware update to fail, or cause the device to stop responding temporarily or permanently. To avoid potential firmware update errors, please plug your Vengeance Gaming keyboard or mouse directly into a USB 2.0 or 1.1 port on your PC.